


Link do produktu: <https://zetrix.pl/filtr-oleju-lf4054-wix-zam-lf4054-p-4580.html>

Filtr oleju LF4054 Wix (zam LF4054)



Cena	31,06 zł
Numer katalogowy	178341897
Kod producenta	6030
Kod EAN	5904608518200

Opis produktu

Indeksy zamienne: F284201310040, HF35284, LF4054, MH390X, LF3687, P557624, LF3625, P553771, P4015, P5067, W96214, 88000922604, 5010664, 61000070005, 6106841, 5205401300, 51055010003, 51055010002, 5502029, 5507547, 3831236, 9450732013, 711922604, 673588, 671160, 8701155447, 9457280400, 5000859, 61671160, 61671600, 5W6017, 5001846639, 61673585, 922604, A15H4123, B7143, B236, AZ22878, 3055270R91, 3136460R91, 551820, 004050740, 0451105067, 0040507408, 0451301001, 0451105182, 2998553, 1173430, 01174421, 004057120, 01181749, 0451105188, 1174421, 1174576, 00MU5074, 00MU5345, 1174577, 119935450, 2998553M1, 0451105001, 0451104015, 1160025, 0009830610, 1901919, 0024164103, 01182552, 0150157520, 1162757, 1111602030900, 05710640, 1162921, 05710634, 01160025, 1182552, 2871722M1, 1621183, 016000001001, 2871722M2, 1174421, ZP505B, W962, W9626, R1350575, ZP3505A, ZP599, W9628, VPD5032, W11701, VPD5052, 1181749, 0814661, WK962, 024564057, MU5345, P779127, MU5074, V37624, BT281, 11116020309, 000504020, P1350575, LF3790, 0003564103, VPD5032?, 024564103, 062114897, 194932128, 194932128, 0013022760, 14564103, 451301001, 451203226, 160000001001, 51820, 6005025477, WL7157, PP123, 128680, A15H4123, 1173430EE, 92089E, 1153430, [#51820E#], A15H4123, 6005025477, 150157520, 6750558686, 2901515, 451105188, 846080160, 814661, 3564103, 6750558806, 6750558476, 6100705, 311361, 504020, 6005019757, 6005019751, 6005019741, 4050740, 40507408, 5710640, 5710634, 5504020, 5502096, 24564057, 9830610, 24164103, 22852900, 4205627, 1907947, 24560060, 500067067, 451105182, 451105067, 246580040, 5000670671, 24564103, 24564058, 451104015 Pasuje do silników: BF6M1013FC - Deutz, BF6M1013ECP - Deutz, BF6M1013FC - Deutz, AKD112E - MWM, AKD112Z - MWM, AKD210.5D - MWM, AKD311Z - MWM, BF6M1013EC - DEUTZ, BF6M1013ECP - DEUTZ, D226-B6 - MWM, D308-3 - MWM, D325-3 - MWM, D327-3 - MWM, D925L3 - MWM, DO824LUE521 - MAN, DO824LUE522 - MAN, DO824LUE523 - MAN, DO826LE501 - MAN, DO826LE502 - MAN, DO826LE503 - MAN, DO826LE524 - MAN, DO826LE527 - MAN, DO826LE530 - MAN, DO826LE531 - MAN, DO826TE512 - MAN, DO826TE520 - MAN, DO826TE522 - MAN, DO826TE523 - MAN, F3L912H - DEUTZ, F3L913H - DEUTZ, F4L912H - DEUTZ, F4L913H - DEUTZ, F6L912 - DEUTZ, F6L913 - DEUTZ, TD226-6 - MWM, TD226-6.2 - MWM, TD226-B6 - MWM, WD210.40 - Steyr, WD311.44/45/46/47 - Steyr, WD408.40 - Steyr, WD408.42 - Steyr, WD408.43 - Steyr, WD410.40 - Steyr, WD412.40 - Steyr, WD412.41 - Steyr, WD610.40 - Steyr, WD610.42 - Steyr, WD610.43 - Steyr, WD610.44 - Steyr, WD611.40/41 - Steyr, WD611.42/43 - Steyr, WD611.85 - Steyr, WD611.85/86 - Steyr, WD611.87/88 - Steyr, WD612.40 - Steyr, WD612.85 - Steyr, WD612.86 - Steyr, WD612.88/89 - Steyr, WD612.96 - Steyr, WD615.84 - Steyr, BF6L912 - Deutz, BF6L913 - Deutz, BF6L913 T - Deutz, BF6M1013E - Deutz, BF6M1013EC - Deutz, BF6M1013FC - Deutz, BL6L912 - Deutz, F4L913 - Deutz, F5L912 - Deutz, F6L812 - Deutz, F6L812D - Deutz, F6L912 - Deutz, F6L913 - Deutz, F8L413 - Deutz Pasuje do modeli: Renault: Tractor Seria Atlas: Atlas 915, Atlas 925, Atlas 926, Atlas 935, Atlas 936 Combine-harvester Deutz Fahr M900 Motor Deutz F.5L.912 , M1002 Motor Deutz F5L.912 , M100, M1102, M1200, M1202, , M1250 Motor F6L.912 , M1080 Motor F5L.912 , M1300, M1300H Motor F6L.913 , M1300 Hydromat Motor F6L.912 , M1302, M1302H, M1302HA , M1302HA Motor Deutz BF6L. Various Seria Claas-Patent: Gigant, Matador, Mercator, Mercator 60, 70, Protector, Senator Moteur Deutz F6L912 , Jaguar 80 SF, Eicher Wotan 1,2 , 3105, 3133, Kramer 914, 1014 , UF1000, UF1003 Motor Deutz F6L.812D , UF1000, UF1001, UF1003 Motor Deutz F6L.912 , 1214 Motor Deutz BF6L.912, Lamborghini: Tractor Seria Victory: Victory 230, Victory 260, Victory Plus 230, Victory Plus 260 Fendt: Tractor Seria Farmer 300: 312, Seria Fav