

Dane aktualne na dzień: 05-04-2025 16:39

Link do produktu: <https://zetrix.pl/zawor-silnika-ssacy-2137301-4153631-deutz-p-5273.html>

Zawór silnika ssący 2137301, 4153631 Deutz



Cena	20,14 zł
Numer katalogowy	178346695
Kod producenta	7130
Kod EAN	5902287086447

Opis produktu

Indeks zamienny: VPA1400, 02133731, 02236960, 4159136, 02137301, 04153631, 6005000693, 6005014208 Pasuje do silników: F2L912, F3L912, F4L912, F5L912, F6L912, F4L913, F6L913, BF6L913 Pasuje do modeli: DX4.50, DX4.51, DX4.61, DX4.70, DX4.71, DX7.10, DX13006, DX140, DX145, DX160, DX6.50, DX7.10, D2506, D2807, D3006, D3607, DX3.10V, DX3.30SC, D3.10SC, D4006, D4007, D4506, D4507, D4507C, D4807, D4807C, D5006, D5206, D5207, D5207C, INTRAC 2002, DX3.50SC, D6007A, D6007C, DX3.60SC, DX3.65SC, DX3.70SC, DX4.10, D5506, D6006, D6206, D6207C, D6507C, D6806, D6807C, D6907C, D7006, D7007, D7007C, D7206, D7207, D7207C, INTRAC 2003, INTRAC 2004, DX3.80SC, DX3.90FS, DX3.90SC, DX4.30, DX4.31, DX80, DX86, DX92, D7807, DX85, DX90, DX110, DX6.05, DX6.10, D10006, D8006, DX120, DX6.30